

FACILITY COMPLIANCE AUDIT REPORT

Division of Waste Management Solid Waste Section

UNIT	TYPE:					
Lined MSWLF	LCID	YW	Transfer	X Compost	SLAS	COUNTY: Forsyth
Closed MSWLF	HHW	White goods	Incin	T&P	FIRM	PERMIT NO.: 34-16T
CDLF	Tire T&P / Collection	Tire Monofill	Industrial Landfill	DEMO	SDTF	FILE TYPE: COMPLIANCE

Date of Audit: May 21, 2009 Date of Last Audit: June 19, 2008

FACILITY NAME AND ADDRESS:

Overdale Road Transfer Station 5000 Overdale Road Winston-Salem, NC 27101

GPS COORDINATES: N: 36.0317 E: -80.2343

FACILITY CONTACT NAME AND PHONE NUMBER:

Mark Bacon, Republic Services of North Carolina, LLC

w: 336-724-0842 c: 336-714-4300

FACILITY CONTACT ADDRESS:

Republic Services of North Carolina, LLC 2875 Lowery Street Winston-Salem, NC 27107-6127

AUDIT PARTICIPANTS:

John Patrone, NCDENR – Solid Waste Section (SWS) Mark Tabaczynski, Republic Services Sandy Lucas, Republic Services – Scale House Operator

STATUS OF PERMIT:

Permit To Operate (PTO) issued September 13, 2007 PTO expires September 13, 2012

PURPOSE OF AUDIT:

Comprehensive Audit

NOTICE OF VIOLATION(S):

None

You are hereby advised that, pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Statute or Regulations. For the violation(s) noted here, you may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE AUDIT REPORT

Division of Waste Management Solid Waste Section

Page 2 of 3

STATUS OF PAST NOTED VIOLATIONS:

None

AREAS OF CONCERN AND COMMENTS:

On May 21, 2009, John Patrone met with Mark Tabaczynski and Sandy Lucas to conduct a comprehensive audit of the Overdale Road Transfer Station in Winston-Salem, Forsyth County.

- 1. The facility is operated by Republic Services of North Carolina, LLC.
- 2. The facility is permitted to receive municipal solid waste (MSW) and construction and demolition (C&D) debris generated within a 50 mile radius of the City of Winston-Salem.
- 3. MSW is transported for disposal to the Uwharrie Environmental Regional Landfill (No. 62-04) in Montgomery County. Alternate disposal sites for waste leaving the transfer facility are Upper Piedmont Regional Landfill (No. 73-04) in Person County and Foothills Regional Landfill (No. 14-03) in Caldwell County.
- 4. The facility site plan and operations plan were verified.
- 5. The following are facility certified Transfer Station Operations Specialist personnel:
 - a. Mark Tabaczynski (TS-2003223), exp. 01/01/12
 - b. Joseph Prestandrea (TS-2005010), exp. 04/05/11
 - c. Leonard Crawford (TS-2007022), exp. 03/13/10
 - d. Mark Bacon (TS-2003224), exp. 01/01/12
 - e. Ricky Craddock (TS-20081236), exp. 12/05/11
 - f. Scott Tennant (TS-20081245), exp. 12/05/11
 - g. Darryl Stratton (TS-2009213), exp. 12/27/12
- 6. The facility maintains daily records of the amount of MSW received. The daily records are summarized into monthly reports. Records were reviewed for 2009 (January through May 20th). The facility throughput is ~ 9,000 TPM.
- 7. The facility ships-out ~ 22 trailers a day (Monday through Friday). During the inspection there were four trailers on-site, three empty and one being filled.
- 8. Waste screening reports were reviewed for July 2008 through May 21st 2009. The facility conducts daily waste screenings. During the inspection the facility conducted a waste screening.
- 9. There appeared to be no build-up of residue on the floor, walls, or ceiling of the transfer station.
- 10. During the inspection no windblown material was observed.
- 11. The facility stores tires and white goods in a roll-off container. When the container is full it is shipped to a facility permitted to accept them.
- 12. Leachate generated by the facility is piped into the City of Winston-Salem sanitary sewer system. The leachate settling tank (located on-site) is routinely pumped-out.
- 13. The facility repaired the gash in the exterior wall of the loading bay area. However, a small hole was observed in the same general area of the exterior wall. The hole should be repaired. It is likely that the metal plates forming the backdrop (atop the loading bay area), which are bent out of position, is causing debris to fall behind the loading trailer and hit the wall of the transfer station. The metal plates forming the backdrop should be replaced.

FACILITY COMPLIANCE AUDIT REPORT

Division of Waste Management Solid Waste Section

Page 3 of 3

Please contact me if you have any questions or concerns regarding this audit report.

John Patrone

Environmental Senior Specialist Regional Representative

Phone: 336-771-5095 Fax: 336-771-4631

			,		
Delivered on : June 1, 2009 by		Hand delivery	X	US Mail	Certified No. [_]
	1				

cc:

Mark Poindexter, Field Operations Branch Supervisor

Jason Watkins, Central Regional Supervisor Donald Herndon, Compliance Officer